

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/29/2020

Submitted Date:

06/29/2020

Document Number:

700700986

FIELD INSPECTION FORM

Loc ID: 322298 Inspector Name: Ramsey, Scott On-Site Inspection: 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
 7 Number of Comments
 2 Number of Corrective Actions
 Corrective Action Response Requested

Operator Information:
 OGCC Operator Number: 10550
 Name of Operator: MUSTANG RESOURCES LLC
 Address: 1660 LINCOLN STREET SUITE 1450
 City: DENVER State: CO Zip: 80264

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, mustang	303-807-5112	dlemon@mustangresourcesllc.com	regulatory manager

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210183	WELL	PR	12/01/2017	GW	045-05078	JUHAN FEDERAL 1-35-6S-94W	PR

General Comment:

COGCC Inspection Report Summary
 On Monday 6/29/20 at approximately 10:30 AM, I, Inspector Scott Ramsey, conducted a follow up inspection at Mustang 1-35-6s-94w, at Location # 322298 in Garfield county Colorado.
 While there, I observed normal production operations. All C/A(s) from previous inspection document # 689302575 have been completed. During this inspection the following possible compliance issues were observed:

- Staining next to tank
- Wheel valve on well head casing side is leaking gas, can hear it when I got on location.

Refer to photograph of observed compliance issue.

I tried to reach Deb Lemon with no answer, I left her a message. I then spoke with Doug Wagoner, pumper with Mustang and explained to him about the leak on the well head. He was going to go to the location and attempt to fix the leak. Doug also said that he would be in touch with me to let me know the status of the problem.
 A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location			
Lease Road:			
Type	Access		
comment:			
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____
Good Housekeeping:			
Type	OTHER		
Comment:	Staining next to production tank		
Corrective Action:	cleanup stained material and review self inspection processes.	Date:	07/06/2020
Type	OTHER		
Comment:	Wheel valve on well head casing side is leaking gas, can hear it when I got on location.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.	Date:	06/30/2020
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type:	Bird Protectors	# 1	corrective date
Comment:			
Corrective Action:			Date:
Type:	Deadman # & Marked	# 3	
Comment:			
Corrective Action:			Date:

Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Venting:

Yes/No	YES	
Comment:	Wheel valve on well head casing side is leaking gas, can hear it when I got on location.	
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 210183 Type: WELL API Number: 045-05078 Status: PR Insp. Status: PR

Producing Well

Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Berms		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700700992	Photos for 1-35-6S-94W	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5186974