

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/23/2020

Submitted Date:

06/29/2020

Document Number:

692402335**FIELD INSPECTION FORM**
 Loc ID 335571 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num: _____
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		COGCCInspectionReports@terraep.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275252	WELL	PR	08/29/2005	GW	045-13501	CLOUGH RWF 11-15	CI
275253	WELL	PR	08/29/2005	GW	045-13502	CLOUGH RWF 311-15	CI
279726	WELL	PR	09/02/2005	GW	045-11081	CLOUGH RWF 411-15	CI
279926	WELL	PR	10/06/2006	GW	045-11111	CLOUGH RWF 421-15	CI
279927	WELL	PR	08/08/2006	GW	045-11112	CLOUGH RWF 422-15	CI
279928	WELL	PR	08/08/2006	GW	045-11113	CLOUGH RWF 511-15	CI
279929	WELL	PR	06/08/2006	GW	045-11114	CLOUGH RWF 332-15	CI
279930	WELL	PR	06/08/2006	GW	045-11115	CLOUGH RWF 22-15	CI
279931	WELL	PR	06/08/2006	GW	045-11116	CLOUGH RWF 12-15	CI
279932	WELL	PR	06/08/2006	GW	045-11117	CLOUGH RWF 522-15	CI
279933	WELL	PR	03/06/2007	GW	045-11118	CLOUGH RWF 21-15	CI
279934	WELL	PR	09/12/2005	GW	045-11119	CLOUGH RWF 321-15	CI

General Comment:

This is a Construction and Stormwater Inspection. Form 42: NOTICE OF CONSTRUCTION: was Filed for this Site, Start Date 6/19/20. Conditions at time of Inspection were Clear Sunny Sky, light breeze from the South at 93 degrees F. Elevation at Site is 5772 ft.

Location ConstructionLocation ID: 335571 CDP: _____
 Comment: This is an expansion of an existing Location to support well completion operations for the ten proposed wells on Loc #335636. Topsoil has been salvaged at SW corner of Location. One piece of heavy equipment was working on shallow cut& fill at time of Insp.

Corrective Action: _____

Date: _____

Form 2A COAs:

Comment:

Corrective Action:

Date:**Wildlife BMPs:****Comment:**

Site is located within Mule Deer Critical Winter Range sensitive wildlife habitat

Corrective Action:

Date:**Stormwater:**

Erosion BMPs	Present	Other BMPs	Present
WADDLES	Yes		

Comments: Erosion BMPs: Wattles have been installed as perimeter controls.

Other BMPs:

Corrective Action:

Date:

BERMS	Yes		
-------	-----	--	--

Comments: Erosion BMPs:

Other BMPs:

Corrective Action:

Date:

DITCHES	Yes		
---------	-----	--	--

Comments: Erosion BMPs:

Other BMPs:

Corrective Action:

Date:**Comment:**

Unnamed ephemeral drainages is located 30 feet to the south, and the other is located approximately 195 feet to the northwest of the existing facility.

**Corrective
Action:****Date:****On Site Inspection (305):**Surface Owner Contact Information:

Name:

Address:

Phone Number:

Cell Phone:

Operator Rep. Contact Information:

Landman Name:

Phone Number:

Date Onsite Request Received:

Date of Rule 306 Consultation:

Request LGD Attendance:

LGD Contact Information:

Name:

Phone Number:

Agreed to Attend:

Summary of Landowner Issues:Summary of Operator Response to Landowner Issues:Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected Facilities

Facility ID: <u>275252</u>	Type: <u>WELL</u>	API Number: <u>045-13501</u>	Status: <u>PR</u>	Insp. Status: <u>CI</u>
Facility ID: <u>275253</u>	Type: <u>WELL</u>	API Number: <u>045-13502</u>	Status: <u>PR</u>	Insp. Status: <u>CI</u>
Facility ID: <u>279726</u>	Type: <u>WELL</u>	API Number: <u>045-11081</u>	Status: <u>PR</u>	Insp. Status: <u>CI</u>
Facility ID: <u>279926</u>	Type: <u>WELL</u>	API Number: <u>045-11111</u>	Status: <u>PR</u>	Insp. Status: <u>CI</u>
Facility ID: <u>279927</u>	Type: <u>WELL</u>	API Number: <u>045-11112</u>	Status: <u>PR</u>	Insp. Status: <u>CI</u>
Facility ID: <u>279928</u>	Type: <u>WELL</u>	API Number: <u>045-11113</u>	Status: <u>PR</u>	Insp. Status: <u>CI</u>
Facility ID: <u>279929</u>	Type: <u>WELL</u>	API Number: <u>045-11114</u>	Status: <u>PR</u>	Insp. Status: <u>CI</u>
Facility ID: <u>279930</u>	Type: <u>WELL</u>	API Number: <u>045-11115</u>	Status: <u>PR</u>	Insp. Status: <u>CI</u>
Facility ID: <u>279931</u>	Type: <u>WELL</u>	API Number: <u>045-11116</u>	Status: <u>PR</u>	Insp. Status: <u>CI</u>
Facility ID: <u>279932</u>	Type: <u>WELL</u>	API Number: <u>045-11117</u>	Status: <u>PR</u>	Insp. Status: <u>CI</u>
Facility ID: <u>279933</u>	Type: <u>WELL</u>	API Number: <u>045-11118</u>	Status: <u>PR</u>	Insp. Status: <u>CI</u>
Facility ID: <u>279934</u>	Type: <u>WELL</u>	API Number: <u>045-11119</u>	Status: <u>PR</u>	Insp. Status: <u>CI</u>

COGCC Comments

Comment	User	Date
Follow up inspection(s) will proceed while construction of location is IN-PROCESS.	colbyl	06/26/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692402344	Insp Photos RI	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5186971