

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

06/29/2020

Submitted Date:

06/29/2020

Document Number:

699302025

**FIELD INSPECTION FORM**
 Loc ID 449137 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10649

Name of Operator: EWS 4 DJ BASIN LLC

Address: 2015 CLUBHOUSE DR SUITE 201

City: GREELEY State: CO Zip: 80634

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
4A, EWS	303-290-9414	wjanes@petrotek.com	ALL INSPECTIONS
Koehler, Bob		bob.koehler@state.co.us	
,		dnr_cogccengineering@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459195	WELL	IJ	07/01/2019	DSPW	123-48766	EWS 4B	IJ

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	plumbed to surface		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 459195 Type: WELL API Number: 123-48766 Status: IJ Insp. Status: IJ

**Underground Injection Control**

UIC Violation: \_\_\_\_\_ Maximum Injection Pressure: \_\_\_\_\_

**UIC Routine**

Inj./Tube: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ MPP \_\_\_\_\_  
 (e.g. 30 psig or -30" Hg) Inj Zone: DJINJ  
 TC: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ Last MIT: 04/04/2019  
 Brhd: Pressure or inches of Hg \_\_\_\_\_ Previous Test Pressure \_\_\_\_\_ AnnMTReq: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Method of Injection: \_\_\_\_\_

Test Type: Verification of Repairs Tbg psi: 0 Csg psi: 13 BH psi: 0

Insp. Status: \_\_\_\_\_

Comment: Witnessed MIT. Starting pressure's before test Tbg psi 0, Csg psi 13, BH psi 0. Started test at approx 1035 hrs.. Starting pressure 2198.7 psi, 5 min 2195.3 psi, 10 min 2193.9 psi, 15 min 2193.2 psi, total loss of 5.5 psi. This MIT is being performed to try to diagnos high annulus pressure.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 6/29/2020 at approximately 1035 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at Expedition Water Solutions location:</p> <p style="text-align: right;">EWS Well # 4B at API</p> <p>#05-123-48766 in Weld County Colorado.</p> <p>While there, I observed an MIT test. Starting pressure's before test Tbg psi 0, Csg psi 13, BH psi 0. Started test at 1035 hrs.. Starting pressure 2198.7 psi, 5 min 2195.3 psi, 10 min 2193.9 psi, 15 min 2193.2 psi, total loss of 5.5 psi. This MIT is being performed to try to diagnos high annulus pressure.</p> <p>During this inspection no compliance issues were observed:</p> <p>See attached photo #.</p> <p>Location is dry, weather is clear.</p> <p>I spoke with Jeremiah Demuth STS with Petrotech during the test procedure.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	06/29/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699302026	loc pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5187000">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5187000</a>