

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/29/2020

Submitted Date:

06/30/2020

Document Number:

690101947

**FIELD INSPECTION FORM**

Loc ID 331031 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Findings:**

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	
Schlagenhauf, Mark		mark.schlagenhauf@state.co. us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257990	WELL	SI	04/01/2019	GW	123-20053	BEELER 22-11	PA

**General Comment:**

[Engineering Integrity Inspection](#); [Flowline Inspection](#)  
[Photos Uploaded](#)

**Inspected Facilities**

Facility ID: 257990 Type: WELL API Number: 123-20053 Status: SI Insp. Status: PA

**Flowline**

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: \_\_\_\_\_ Material: \_\_\_\_\_  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules (check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: Well (Beeler 22 -11) has been plugged and abandoned; COGCC form 42 notice of start of plugging operations Doc #402258263 was received on 12/09/2019. COGCC form 42 Flowline Pre Abandonment - 30-day notice Doc #402317023 was updated on 6/24/2020. COGCC form 44 (off location flowline abandonment) notice Doc #402358341 was received on 03/31/2020. Flowline risers have been removed at both the (PA) well and facility. The shared facility/ battery services 2 remaining wells; Beeler 22 -12, 22-13 (SI/ OOSLAT). No CA's identified during this field inspection.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101950	Signage at tank battery	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5187335">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5187335</a>
690101951	Flowlines at inlet to horizontal separator (OOSLAT)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5187336">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5187336</a>
690101952	Well location (PA); No flowline risers	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5187337">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5187337</a>