

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/24/2020

Submitted Date:

06/30/2020

Document Number:

690101948

FIELD INSPECTION FORM

Loc ID 336613 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	
Schlagenhauf, Mark		mark.schlagenhauf@state.co. us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250808	WELL	PR	02/20/2019	GW	123-18611	HSR-KAMMERZELL 15-25	PA

General Comment:

[Engineering Integrity Inspection; Flowline Inspection](#)
[Photos Uploaded](#)

Inspected Facilities

Facility ID: 250808 Type: WELL API Number: 123-18611 Status: PR Insp. Status: PA

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: Off location flowline abandonment has not been completed. Off location flowlines are shut in at facility/ inlet to heated horizontal separators (OOSLAT applied). COGCC form 42 Flowline Pre Abandonment - 30-day notice Doc #402364808 was updated on 6/23/2020. COGCC form 44 (off location flowline abandonment) notice Doc #402358341 was received on 03/31/2020. The shared facility/ battery services 3 additional wells; Boos 20-25, 37-25, Kammerzell 16-25 (Flowlines SI/ OOSLAT).

Corrective Action:

Date:

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101953	Signage at battery	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5187513
690101954	Flowline at inlet to horizontal separator (OOSLAT)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5187514
690101955	Off location flowline marked (Pinflagged)	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5187515