



**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:	<input type="text"/>	Date:	
Corrective Action:	<input type="text"/>		

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

**Equipment:**

Type: Bradenhead	# 1		corrective date
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**Facility ID: 241766 Type: WELL API Number: 123-09555 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>  On (6/30/2020) at approximately (10:45 Hrs), I, Inspector (Abe Serna),  Conducted an on-site inspection at (Musick-McClintock#2) (KPK Energy), at  (Location #318633) in (Weld County) Colorado.  While there, I observed a (PR Well)  During this inspection no compliance issues were observed.  No follow up on this site inspection needs to be conducted.  This is a summary of inspection report.  Continuing Inspector Training.</p>	sernaa	06/30/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698701632	Photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5187696">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5187696</a>