

Inspection Photos
Location Name: Uprrr 60 Pan Am E
Location ID: 320083



Photo #1 Tank

Photo #2 Tank

Inspection Photos
Location Name: Uprrr 60 Pan Am E
Location ID: 320083



Photo #3 stained soil in berm of produced water

Photo #4 stained soil from berm to separator, ECD

Inspection Photos
Location Name: Uprrr 60 Pan Am E
Location ID: 320083



Photo #5 separator.

Photo #6 stained soil up to separator

Inspection Photos
Location Name: Uprrr 60 Pan Am E
Location ID: 320083



Photo #7 stained soil under separator and missing chunk if gasket in separator fire box.



Photo #8 separator and weeds.

Inspection Photos
Location Name: Uprrr 60 Pan Am E
Location ID: 320083



Photo #9 vertical separator, meter run and weeds

Photo #10 well head and weeds