

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	STORAGE OF SUPL		
Comment:	Unused equipment (used oil buckets).		
Corrective Action:	Unused equipment. Per rule 603.f. Corrective Action Date 7/24/2020 See attached photos # 7 & 8.	Date:	07/24/2020
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment (plastic piping).		
Corrective Action:	Unused equipment. Per rule 603.f. Corrective Action Date 7/24/2020 See attached photos # 7 & 8.	Date:	07/24/2020
Type	WEEDS		
Comment:	Weeds.		
Corrective Action:	Location is within a designated setback location, remove Weeds per Rule 603 f. Corrective Action Date 7/10/2020. See attached photos #1, 3, 5 & 9.	Date:	07/10/2020

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

Type: Plunger Lift	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			

Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	OTHER		
Comment:	pit				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		39.975702,-104.530120
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 202314 Type: WELL API Number: 001-07719 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Comment: Appears to be plumbed to surface.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Wednesday June 24, 2020 at approximately 8:45am, I, Inspector Chane Finkenbinder, Conducted an on-site inspection at Abbott 43-10 Painted Pegasus Petroleum, at API #001-07719 in Adams County Colorado. While there, I observed a Shut in well, During this inspection the following possible compliance issues were observed: Weeds. Location is within a designated setback location, remove Weeds per Rule 603 f. Corrective Action Date 7/10/2020. See attached photos #1, 3, 5 & 9. Building(s) in disrepair. Inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Corrective Action Date 7/24/2020 See attached photos #.3, 4 & 5. Unused equipment (used oil buckets and plastic piping). Unused equipment. Per rule 603.f. Corrective Action Date 7/24/2020 See attached photos # 7 & 8. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	finkenbc	06/29/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700900203	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5187968