

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

06/30/2020

Submitted Date:

06/30/2020

Document Number:

700701000

FIELD INSPECTION FORM

 Loc ID 335001 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 10531
 Name of Operator: GRIZZLY OPERATING LLC
 Address: 5847 SAN FELIPE #3000
 City: HOUSTON State: TX Zip: 77057
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		scollett@grizzlyenergyllc.com	
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
291094	WELL	PR	11/10/2008	GW	045-14303	CIRCLE B LAND 11A-35-692	PR
291095	WELL	PR	11/08/2008	GW	045-14302	CIRCLE B LAND 11D-35-692	PR
291097	WELL	PR	11/12/2008	GW	045-14301	CIRCLE B LAND 12C-35-692	PR
291099	WELL	PR	11/05/2008	GW	045-14300	CIRCLE B LAND 12B-35-629	PR
294937	WELL	PR	11/14/2008	GW	045-15639	CIRCLE B LAND 13D-35-692	PR
294938	WELL	PR	11/04/2008	GW	045-15638	CIRCLE B LAND 11B-35-692	PR

General Comment:

COGCC Inspection Report Summary
 On Tuesday 6/30/20 at approximately 2:30 PM, I, Inspector Scott Ramsey, conducted a High risk inspection at Grizzly Circle B 1, at Location # 335001 in Garfield county Colorado.
 While there, I observed normal production operations. All C/A(S) from previous inspection document # 700700669 have been completed.
 This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Emergency Contact Number:	
Comment:	911
Corrective Action:	
	Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

Multiple Spills and Releases?

Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	SEPARATOR		
Comment:			
Corrective Action:			Date:

Equipment:			corrective date
Type: Bird Protectors	# 8		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:

Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 6		
Comment:	All meters calibrated on location within a year.		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	chemical tanks at seperators		
Corrective Action:			Date:
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	500 BBLs	HEATED STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	Ignitor/Combustor	
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	291094	Type:	WELL	API Number:	045-14303	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	291095	Type:	WELL	API Number:	045-14302	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	291097	Type:	WELL	API Number:	045-14301	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	291099	Type:	WELL	API Number:	045-14300	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	294937	Type:	WELL	API Number:	045-15639	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				
Facility ID:	294938	Type:	WELL	API Number:	045-15638	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	producing								
Corrective Action:					Date:				

Environmental

Spill/Remediation:

Comment:

Corrective Action: Date:

Emission Control Burner (ECB): YES

Comment:

Pilot: ON Wildlife Protection Devices (fired vessels): YES

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Ditches				
		Gravel				
Berms		Culverts				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700701006	photos for Circle B1	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5187967