

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

06/24/2020

Submitted Date:

06/30/2020

Document Number:

699700166

**FIELD INSPECTION FORM**

Loc ID 335107 Inspector Name: Heil, John On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Gardner, Mike		mgardner@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476937	SPILL OR RELEASE	CL	05/27/2020		-	SPILL/RELEASE POINT	EI

**General Comment:**

On June 24, 2020, COGCC Staff John Heil conducted an environmental field inspection of TEP ROCKY MOUNTAIN LLC (TEP operator #96850) Location ID 335107 GV 17-32-696 Pad and Spill/Release ID 476937.

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
Comment:					
Corrective Action:					Date:

Paint

Condition	<input type="text"/>
Other (Content)	<input type="text"/>
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	<input type="text"/>
Comment:	<input type="text"/>
Corrective Action:	Date:

**Flaring:**

Type	<input type="text"/>
Comment:	<input type="text"/>
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 476937 Type: SPILL OR API Number: - Status: CL Insp. Status: EI

**Environmental**

**Spills/Releases:**

Type of Spill: \_\_\_\_\_ Estimated Spill Volume: \_\_\_\_\_

Comment: 5/26/2020 A hole in the base of a 300 bbl produced water tank released 110 bbls of fluids into a metal, liner secondary containment structure. See Form 19 Spill/Release Report Doc #402406480 for details. 6/24/2020 COGCC John Heil conducted a visual inspection of in and around the tank battery. A residual staining ring was observed within the tank battery secondary containment.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699700167	20200624 Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5188073">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5188073</a>