

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/01/2020

Submitted Date:

07/01/2020

Document Number:

698701635

FIELD INSPECTION FORM

Loc ID 435930 Inspector Name: Serna, Abe On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435927	WELL	PR	03/01/2018	OW	123-38862	EAGLE E 14-63-1HN	PR
435928	WELL	PR	04/01/2018	OW	123-38863	EAGLE E 14-79HN	PR
435929	WELL	SI	10/01/2019	OW	123-38864	SENECA E 15-72-1HN	SI
435931	WELL	PR	03/01/2018	OW	123-38865	SENECA E 15-72-1HC	PR
435932	WELL	PR	03/01/2018	OW	123-38866	TAHOMA E 22-69HC	PR
435933	WELL	SI	02/01/2020	OW	123-38867	EAGLE E 14-62-1HN	SI
435934	WELL	PR	03/01/2018	OW	123-38868	RELIANCE E 23-79HN	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Vertical Separator	# 15		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	#		
Comment:	40		
Corrective Action:		Date:	
Type: Emission Control Device	# 18		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	#		
Comment:	34		
Corrective Action:		Date:	
Type: Plunger Lift	# 7		

Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:	Appears to be plumbed to surface.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	#		
Comment:	22		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1	OTHER	BV CONCRETE		,
Comment:	12 bbl				
Corrective Action:					Date:

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	500 BBLs	STEEL AST		,
Comment:	Shares containment with crude oil tanks.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	18	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		
		Date:

Inspected Facilities				
Facility ID: <u>435927</u>	Type: <u>WELL</u>	API Number: <u>123-38862</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: <u>PR</u>				
Corrective Action:				Date:
Facility ID: <u>435928</u>	Type: <u>WELL</u>	API Number: <u>123-38863</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: <u>PR</u>				
Corrective Action:				Date:
Facility ID: <u>435929</u>	Type: <u>WELL</u>	API Number: <u>123-38864</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: <u>SI</u>				
Corrective Action:				Date: _____
Facility ID: <u>435931</u>	Type: <u>WELL</u>	API Number: <u>123-38865</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: <u>PR</u>				
Corrective Action:				Date:
Facility ID: <u>435932</u>	Type: <u>WELL</u>	API Number: <u>123-38866</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: <u>PR</u>				
Corrective Action:				Date:
Facility ID: <u>435933</u>	Type: <u>WELL</u>	API Number: <u>123-38867</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: <u>SI</u>				
Corrective Action:				Date: _____
Facility ID: <u>435934</u>	Type: <u>WELL</u>	API Number: <u>123-38868</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Producing Well				
Comment: <u>PR</u>				
Corrective Action:				Date:
COGCC Comments				

Comment	User	Date
<p>COGCC Inspection Report Summary On (7/1/2020) at approximately (Military Time 09:00 HRS), I, Inspector (Abe Serna), Conducted an on-site inspection at (Reliance E#23-79HN) (Noble Energy), at (Location #435930) in (Weld County) Colorado. While there, I observed a (PR Well) During this inspection no compliance issues were observed. No follow up on this site inspection needs to be conducted. This is a summary of inspection report. Continuing Inspector Training.</p>	sernaa	07/01/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698701636	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5188888