

Location Name: – Investment Equipment LLC – Ward Kincheloe 1 Battery
Inspection Date: 06/29/2020



Photo # 1 –



Location Name: – Investment Equipment LLC – Ward Kincheloe 1 Battery
Inspection Date: 06/29/2020



Photo # 2 – Produced water pits are dry, no water inflow

Location Name: – Investment Equipment LLC – Ward Kincheloe 1 Battery
Inspection Date: 06/29/2020



Photo # 3 – South side of tank battery. Yellow containment bucket on its side, stained soil on east side of battery

Location Name: – Investment Equipment LLC – Ward Kincheloe 1 Battery
Inspection Date: 06/29/2020



Photo # 4 – South side of tank battery. Yellow containment bucket on its side, oil stained soil



Location Name: – Investment Equipment LLC – Ward Kincheloe 1 Battery
Inspection Date: 06/29/2020



Photo # 5 – South side of tank battery oil stained soil around produced water tank



Location Name: – Investment Equipment LLC – Ward Kincheloe 1 Battery
Inspection Date: 06/29/2020



Photo # 6 – East side of tank battery oil stained soil around produced water tank

Location Name: – Investment Equipment LLC – Ward Kincheloe 1 Battery
Inspection Date: 06/29/2020



Photo # 7 – West side of tank battery former separator concrete foundation requires removal and disposal

