

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/01/2020

Submitted Date:

07/01/2020

Document Number:

688308138**FIELD INSPECTION FORM**Loc ID 434358 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10706Name of Operator: D90 ENERGY LLCAddress: 202 TRAVIS STREET #402City: HOUSTON State: TX Zip: 77002**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:8 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Spear, Sam	(970) 554-1988	sam@d90energy.com	All Inspections
Kosola, Jason		jason.kosola@state.co.us	COGCC EPS
Silverman, Daniel	713-227-0391	dsilverman@d90energy.com	President
Oakes, Kevin	713-227-0391	kevin@d90energy.com	Designated Agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434359	WELL	PR	06/11/2015	OW	073-06552	BIG SKY 5-11	SI

General Comment:**Flowline Spill Inspection**

Inspector received a call from operator at ~9:00 am on 7/1/2020 about a flowline spill at the Big Sky 5-11 wellhead of approximately 1 bbl oil and 4-5 bbls produced water outside of containment. Oil and water left location and affected a small amount of dryland corn. Well was SI. See attached photos. Form 19I was submitted by operator and spill was cleaned up and stained soil removed from location in rollofs (operator sent photos) to be properly disposed. Repair work will be done on Monday and root caused to be determined. Form 19S is due in 10 days of spill date.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 303-638-6096

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	
PW/CO	Flow Line	>= 5 bbls	
Comment:	~1 bbls crude oil and 4-5 bbls produced water spilled from flowline at wellhead. Form 19I was submitted by operator and stained soils were removed from location on the same day as the spill (see attached photos).		
Corrective Action:	Submit Form 19S in 10 days from spill to update information and provide root cause and lessons learned. Contact COGCC EPS.		Date: 07/13/2020

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 434359 Type: WELL API Number: 073-06552 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI for spill

Corrective Action: _____

Date: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688308139	D90 Energy LLC, Big Sky 5-11	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5189198