

Inspection Photos

API: 05-009-06231

Operator: SOVEREIGN OPERATING COMPANY

Inspection Date: 6/22/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06231 | Date: 6/22/2020

Inspection Photos



Photo 1. Facing east along the former access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06231 | Date: 6/22/2020

Inspection Photos



Photo 2. This area is being farmed around the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06231 | Date: 6/22/2020

Inspection Photos



Photo 3. Facing east toward the well site. There areas bare of vegetation and undesirable weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06231 | Date: 6/22/2020

Inspection Photos



Photo 4. Facing east outside of the location. This area is being farmed around however, desirable vegetation is well established outside of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06231 | Date: 6/22/2020

Inspection Photos



Photo 5. Facing west at the location. There are areas bare of vegetation and there are also areas with desirable vegetation establishment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06231 | Date: 6/22/2020

Inspection Photos



Photo 6. View of ground cover which shows rock debris that remains which was not noticed in the surrounding undisturbed area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06231 | Date: 6/22/2020

Inspection Photos



Photo 7. North of the location facing east. The crop field can be seen in left portion of photo and the grassland area near the location is in the right of the photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 05-009-06231 | Date: 6/22/2020