

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/01/2020

Submitted Date:

07/02/2020

Document Number:

699801360

FIELD INSPECTION FORM

Loc ID: 322527 Inspector Name: De Paolo, Corey On-Site Inspection: 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10341
Name of Operator: PUCKETT LAND COMPANY
Address: 5460 S. QUEBEC STREET - STE #250
City: GREENWOOD State: CO Zip: 80111

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 11 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Stearns, Eric		ericstearns@puckettland.com	
, Engineering		dnr_cogccengineering@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210721	WELL	SI	01/01/2018	GW	045-06479	CATHEDRAL CREEK 2	SI

General Comment:

[COGCC Inspection Report Summary](#)
On Wednesday 7/1/20 at approximately 11:00 hours I, Inspector Corey De Paolo, Conducted an on-site inspection at PUCKETT LAND COMPANY CATHEDRAL CREEK67S97W /11NWNE, Location #322527 in Garfield County Colorado.
During this inspection the following possible compliance issues were observed: Workover rig attempted to load the hole with 107 bbls of water on top of the cast iron bridge plug landed at 6,790 ft. The well never loaded and took upwards of 200 bbls. Unable to perform MIT with a corrective action date of 10/1/20.

The following day on July 2nd Eric Stearns with Puckett Land Company informed me that they had located the leak in the casing at 2391 to 2424 feet and were deciding whether to fix the leak and retest or work on plugging and abandoning the well.
This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:	Chemical tank		
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:	Hog panels		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:			Date:

Equipment:			corrective date
Type: Other	# 1		
Comment:	BOP and accumulator		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Workover rig		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Chemical tank		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Rig tank		
Corrective Action:			Date:
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Rig pump		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 210721 Type: WELL API Number: 045-06479 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Operator unable to perform MIT due to not being able to load the well with fluid.

Corrective Action: All non-injection wells which lack mechanical integrity, as determined through a mechanical integrity test or other means, shall be repaired or plugged and abandoned. Repair and retest or plug and abandon well.

Date: 10/01/2020

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
		Gravel	Pass			
		Culverts	Pass			
Gravel	Pass					
Berms	Pass					
		Berms	Pass			
Ditches	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699801373	Photos for Insp. #699801360	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5189999