

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/02/2020

Submitted Date:

07/02/2020

Document Number:

700701022

FIELD INSPECTION FORM

 Loc ID 334694 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num:
Operator Information:

OGCC Operator Number: 10531

Name of Operator: GRIZZLY OPERATING LLC

Address: 5847 SAN FELIPE #3000

City: HOUSTON State: TX Zip: 77057

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, Grizzly		aaxelson@grizzlyenergyllc.com	
, Grizzly		scollett@grizzlyenergyllc.com	
, Grizzly		sghan@grizzlyenergyllc.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
259900	WELL	PR	09/01/2004	GW	045-07795	MAMM CREEK FEDERAL 11-33	PR
259933	WELL	PR	10/04/2001	GW	045-07802	MAMM CREEK FEDERAL 14-33	PR
280247	WELL	PR	09/16/2006	GW	045-11224	OKAGAWA FEDERAL 14C-33-692	PR
280257	WELL	PR	09/15/2006	GW	045-11227	OKAGAWA FEDERAL 24B-33-692	PR
280258	WELL	PR	09/16/2006	GW	045-11226	OKAGAWA FEDERAL 23A-33-692	PR

General Comment:

COGCC Inspection Report Summary

On Thursday 7/2/20 at approximately 12:30 PM, I, Inspector Scott Ramsey, conducted a routine inspection at Grizzly Okagawa Federal 66S92W33SESW, at Location # 323945 in Garfield county Colorado.

While there, I observed normal production operations.

This is a summary of inspection report.

Location					
Lease Road:					
Type	Access				
comment:					
Corrective Action:					Date:
Overall Good: <input checked="" type="checkbox"/>					
Signs/Marker:					
Type	TANK LABELS/PLACARDS				
Comment:					
Corrective Action:					Date:
Type	WELLHEAD				
Comment:					
Corrective Action:					Date:
Emergency Contact Number:					
Comment:	911				Date:
Corrective Action:					Date: _____
Good Housekeeping:					
Type	DEBRIS				
Comment:					
Corrective Action:					Date:
Overall Good: <input checked="" type="checkbox"/>					
Spills:					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
Fencing/:					
Type	WELLHEAD				
Comment:					
Corrective Action:					Date:
Equipment:					
Type:	Plunger Lift	# 5			corrective date
Comment:					
Corrective Action:					Date:
Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	200 BBLS	STEEL AST		,
Comment:	tank is conected to braden head				
Corrective Action:					Date:

Paint				
Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				
Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:
Venting:				
Yes/No	NO			
Comment:				
Corrective Action:				Date:
Flaring:				
Type				
Comment:				
Corrective Action:				Date:

Inspected Facilities									
Facility ID:	<u>259900</u>	Type:	<u>WELL</u>	API Number:	<u>045-07795</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>259933</u>	Type:	<u>WELL</u>	API Number:	<u>045-07802</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>280247</u>	Type:	<u>WELL</u>	API Number:	<u>045-11224</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>280257</u>	Type:	<u>WELL</u>	API Number:	<u>045-11227</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>280258</u>	Type:	<u>WELL</u>	API Number:	<u>045-11226</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Culverts				
Gravel		Ditches				
		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700701027	Photos for Okagawa Federal 66S92W33SESW	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5190004