

Inspection Photos

June 30, 2020

Location Name: Pintail SWD Location ID 446527; Spill ID 477094



Sign at Hwy for Location ID: 446527.



Sign at entrance to Location ID: 446527.



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos

June 30, 2020

Location Name: Pintail SWD Location ID 446527; Spill ID 477094



Suspected area of leak is behind the insulation and to the right of the electrical conduit.



Suspected area of leak is behind the insulation and to the right of the electrical conduit.



Inspection Photos

June 30, 2020

Location Name: Pintail SWD Location ID 446527; Spill ID 477094



Pipe and stair supports deteriorating, metal sheeting on liner.



Trash/debris metal sheeting on liner. Note the folds in liner.



Inspection Photos

June 30, 2020

Location Name: Pintail SWD Location ID 446527; Spill ID 477094



Concrete weight/anchor with rebar (trash/debris) with potential to puncture or compromise liner.



Trash and folds in liner.



Inspection Photos

June 30, 2020

Location Name: Pintail SWD Location ID 446527; Spill ID 477094



Concrete weight/anchor with rebar (trash/debris) with potential to puncture or compromise liner.



Trash and folds in liner.



Inspection Photos

June 30, 2020

Location Name: Pintail SWD Location ID 446527; Spill ID 477094



Oil pooling on liner.



Salt staining on liner throughout secondary containment.



Inspection Photos

June 30, 2020

Location Name: Pintail SWD Location ID 446527; Spill ID 477094



No observable staining outside of secondary containment.



Surface staining at load out.



Inspection Photos

June 30, 2020

Location Name: Pintail SWD Location ID 446527; Spill ID 477094



Surface staining at load out.



Surface staining.

Inspection Photos

June 30, 2020

Location Name: Pintail SWD Location ID 446527; Spill ID 477094



Concrete weight/anchor with rebar and valve handles with potential to puncture or compromise liner. Oil pooling on liner.



Concrete weight/anchor with other debris on liner with the potential to puncture or compromise liner. Note how liner is wind blown with folds.



Inspection Photos

June 30, 2020

Location Name: Pintail SWD Location ID 446527; Spill ID 477094



Concrete weight/anchor with other debris on liner with the potential to puncture or compromise liner. Note how liner is wind blown with folds.



Salt staining on liner throughout secondary containment.

