

# Inspection Photos

API: 071-06798

Operator: EVERGREEN NATURAL RESOURCES

Inspection Date: 6/30/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06798 | Date: 6/30/2020

## Inspection Photos



**Photo 1.** Facing southeast along the access road. There is erosion occurring along the side of the road and there are no BMP's In this area along the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06798 | Date: 6/30/2020



## Inspection Photos



**Photo 2.** Facing east along the road. There is a long stretch of road which does not have culverts or BMP's which is contributing to the volume of stormwater directed down the side of the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06798 | Date: 6/30/2020



## Inspection Photos



**Photo 3.** There is a culvert at this point along the road which has filled in with sediment.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06798 | Date: 6/30/2020



## Inspection Photos



**Photo 4.** Facing back toward the southwest near the top of the hill toward the location. These rock checkdamns have filled in with sediment and are displaced.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06798 | Date: 6/30/2020



## Inspection Photos



**Photo 5.** Facing southeast along the access road. Stormwater diverted along the road is causing erosion in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06798 | Date: 6/30/2020



## Inspection Photos



**Photo 6.** Facing back toward the west. There is a long stretch of road (from red arrow) which does not have BMP's which is contributing to the volume of stormwater directed down the side of the road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06798 | Date: 6/30/2020



## Inspection Photos



**Photo 7.** Facing southeast along the opposite side of the road. Rock check damns have failed in this area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06798 | Date: 6/30/2020



## Inspection Photos



**Photo 8.** Facing northeast toward the location. Well sign is posted at the meter shed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06798 | Date: 6/30/2020