

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/02/2020

Submitted Date:

07/07/2020

Document Number:

700402268**FIELD INSPECTION FORM**Loc ID 476982 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 99999Name of Operator: OLD OPERATORS - STATUS UNKNOWNAddress: SEE COMMENT LINE IN WELLCity: XXXXXXX State: XX Zip: _____**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Chollett, Shannon		shannon.chollett@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
476968	WELL	TA	06/18/2020	OW	103-12416	RUnknown 33-5	TA

General Comment:

Inspection of open hole well with no known operator. Currently not in orphan well program. Nearest buisness 1490' from well. Nearest occupied residence 900' from well.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: **Good Housekeeping:**Type Comment: Corrective Action: Date: Overall Good: ☐**Spills:**Type In Containment: Comment: ☐ Multiple Spills and Releases?**Venting:**Yes/No Comment: Corrective Action: Date: **Flaring:**Type Comment: Corrective Action: Date:

Inspected FacilitiesFacility ID: 476968 Type: WELL API Number: 103-12416 Status: TA Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Open hole abandon well. The 8" diameter casing has no surface damage. A rock dropped in casing was heard falling for 35 seconds until it was too faint to hear. Well located 150' from the road in flat terrain.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT

Optical Gas Imaging SurveySurvey Type: RoutineCurrent Operations: ☐ Production ☐ Workover ☐ Flowback ☐ Referred to APCD

GPS(entrance of location): Lat: _____ Long: _____

Wind: Light Speed: _____ (mph) Direction From: _____ Weather: _____ Temperature: (F)

Assisting Staff: _____ Camera #: _____

☐ Visible Smoke ☐ Referred to CDPHE

Times Surveyed

Equipment Surveyed

Time Survey Start	AM/PM	Time Survey End	AM/PM	Equipment
5:35	PM	5:40	PM	Wellhead(s)

Comment: FLIR infrared images & movies acquired. A small amount of gas was observed venting. Gas odor detected from 10' away.Corrective
Action:

Date:

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700402269	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5191274
700402270	infrared movie of gas venting	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5191275
700402271	infrared HSM movie of gas venting	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5191276