

Inspection Photos  
Operator: BP America  
API: 067-08790  
Date: 7/6/2020



Photo 1. View of the project area from the southern edge facing northward.





Photo 2. View of the northern fill slope from the northwestern corner facing eastward. Revegetation is progressing with grasses such as smooth brome, western wheatgrass, and crested wheatgrass.






Photo 3. View of dense, wilting musk thistles within the northern project area.






Photo 4. View of dense Russian knapweeds within the southern project area. Approximately 1000 individuals observed. Many appear to be recently herbicide treated, however additional treatments will be needed in 2020.





Photo 5. Google Earth aerial imagery that shows directional flow of stormwater runoff from the northern edge of the well pad that flows into the Pine Gulch stream.





Photo 6. View of the stormwater run-down shown in Photo 5, facing downslope, toward where it flows into the Pine Gulch stream.





Photo 7. View of the reference area, comprised of open pinyon and juniper woodland with black sage understory and a mix of native and non-native grasses and forbs such as smooth brome and Navajo tea.