

Inspection Photos
Operator: BP America
API: 067-08377
Date: 7/6/2020



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with grasses such as smooth brome, western wheatgrass, and crested wheatgrass. Russian knapweeds are scattered within the southern project area.



Photo 3. View of the eastern project area facing northward.



Photo 4. View of Russian knapweed infestation within the southeastern project area. Approximately 2000 individuals observed.



Photo 5. View of the reference area, comprised of pinyon and juniper woodland with gambel oak and a mix of native and forbs such as blue grama, Sandberg bluegrass, and Navajo tea.