

Inspection Photos
Operator: Catamount Operating
API: 067-05455
Date: 7/6/2020



Photo 1. View of the western project area from the center of the well pad facing westward. Wattles are trenching and staked in place, and appear to be functioning.



Photo 2. View of weed treatment within the central project area facing southward. Weed vegetation such as kochia and Russian thistle, is marked with green herbicide dye.



Photo 3. View of the southeastern project area facing southward. Project area is seeded and mulched.



Photo 4. View of the reference area, comprised of open sagebrush shrubland with a mixture of grasses and forbs in the understory such as western wheatgrass, crested wheatgrass, and penstemon.