

Inspection Photos
Facility Name: Edward Hemple Unit 1
Facility ID: 459573 (Remediation 12591)



Photo 1 – Weeds around monitoring wells



Photo 2 – Partially mowed weeds around monitoring wells

Inspection Photos

Facility Name: Edward Hemple Unit 1

Facility ID: 459573 (Remediation 12591)



Photo 3 – Broken monitoring well



Photo 4 – Broken monitoring well