

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/08/2020

Submitted Date:

07/09/2020

Document Number:

690101966**FIELD INSPECTION FORM**Loc ID 330659 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

2 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	
Schlagenhauf, Mark		mark.schlagenhauf@state.co. us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251622	WELL	SI	07/01/2019	GW	123-19425	BASS N 14-9	TA

**General Comment:**

Engineering Integrity Inspection; Flowline Inspection

Photos Uploaded

**Inspected Facilities**Facility ID: 251622 Type: WELL API Number: 123-19425 Status: SI Insp. Status: TA**Flowline**

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: \_\_\_\_\_ Material: \_\_\_\_\_  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well (Bass N 14-9) is Temporarily Abandoned; off location flowline disconnected from wellhead. OOSLAT observed in place on flowline valves at wellhead and inlet to horizontal separator. COGCC form 42 Flowline Pre Abandonment - 30-day notice Doc #402364881 was received on 04/08/2020; updated on 6/18/2020. The facility services multiple wells; flowlines observed LOTO at horizontal separators and equipment. Noble Energy personnel were not on location; NO CA's identified during this field inspection.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101969	Signage at wellhead	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5193613">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5193613</a>
690101970	TA well; flowline disconnected (OOSLAT)	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5193614">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5193614</a>
690101971	Flowline inlet at HS; OOSLAT	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5193615">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5193615</a>