

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/09/2020

Submitted Date:

07/09/2020

Document Number:

699302119

FIELD INSPECTION FORM
 Loc ID 432232 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

16 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------------|---------------------------------|
| , | | COGCCinspections@anadarko.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------------|-------------|
| 432227 | WELL | PR | 01/28/2014 | OW | 123-37025 | KUNZMAN FEDERAL 13N-8HZ | PR |
| 432229 | WELL | PR | 07/01/2019 | OW | 123-37027 | KUNZMAN 29N-5HZ | PR |
| 432230 | WELL | PR | 07/01/2019 | OW | 123-37028 | KUNZMAN 4N-5HZ | PR |
| 432233 | WELL | PR | 02/28/2014 | OW | 123-37030 | KUNZMAN FEDERAL 35N-8HZ | PR |
| 432234 | WELL | PR | 01/28/2014 | OW | 123-37031 | KUNZMAN 14N-8HZ | PR |
| 432236 | WELL | PR | 10/01/2019 | OW | 123-37032 | KUNZMAN FEDERAL 30N-5HZR | PR |
| 432237 | WELL | PR | 01/28/2014 | OW | 123-37033 | KUNZMAN FEDERAL 13C-8HZ | PR |
| 432238 | WELL | PR | 01/22/2014 | OW | 123-37034 | KUNZMAN 3C-5HZ | PR |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|--------------|-------|--|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Adequate x 4 | | |
| Corrective Action: | | Date: | |

| | |
|---------------------------|-------------|
| Emergency Contact Number: | |
| Comment: | |
| Corrective Action: | Date: _____ |

| | | | |
|---------------------------|---|-------|------------|
| Good Housekeeping: | | | |
| Type | OTHER | | |
| Comment: | Stained soil under leaking valve on the Kunzman 4N-5HZ API # 05-123-37028 | | |
| Corrective Action: | Comply with Rule 1002..(2).D, Conduct maintenance on equipment, cleanup stained material and review self inspection processes. | Date: | 07/14/2020 |
| Type | OTHER | | |
| Comment: | Leaking valve on the Kunzman 4N-5HZ API # 05-123-37028 | | |
| Corrective Action: | Comply with Rule 605.d Mechanical issues Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition. | Date: | 07/24/2020 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

| | | | |
|--------------------|--------------|-------|--|
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Ag fence x 8 | | |
| Corrective Action: | | Date: | |

| | | | |
|---------------------------|--|-------|-----------------|
| Equipment: | | | corrective date |
| Type: Bradenhead | # 8 | | |
| Comment: | all appear to be plumbed to surface | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 9 | | |
| Comment: | automation, electric panel and transformer | | |
| Corrective Action: | | Date: | |
| Type: Plunger Lift | # 8 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

| |
|--|
| |
|--|

| Inspected Facilities | | | | | | | | | |
|-----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 432227 | Type: | WELL | API Number: | 123-37025 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 432229 | Type: | WELL | API Number: | 123-37027 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 432230 | Type: | WELL | API Number: | 123-37028 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 432233 | Type: | WELL | API Number: | 123-37030 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 432234 | Type: | WELL | API Number: | 123-37031 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 432236 | Type: | WELL | API Number: | 123-37032 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 432237 | Type: | WELL | API Number: | 123-37033 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |
| Facility ID: | 432238 | Type: | WELL | API Number: | 123-37034 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | PR | | | | | | | | |
| Corrective Action: | | | | | | Date: | | | |

COGCC Comments

| Comment | User | Date |
|---|--------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Thursday 7/9/2020 at approximately 1135 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location:</p> <p style="text-align: center;">Kunzman Federal 35N-8HZ at</p> <p>Location #432232 in Weld County Colorado.</p> <p>While there, I observed a Multi-well pad.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>605.d Mechanical issue: Leaking valve on the Kunzman 4N-5HZ API # 05-123-37028, CA date 7-24-2020 see photo 12.</p> <p>1002..(2).D stained soil: Stained soil under leaking valve on the Kunzman 4N-5HZ API # 05-123-37028, CA date 7-14-2020 see photos 11,12 and 13.</p> <p>See attached photos.</p> <p>Location is dry, weather is clear.</p> <p>At 1145 hrs I spoke with Joe, Steve and Shannon due to issue with phone transfer all are Kerr McGee dispatch operators and gave them the well name, API and Location numbers along with cross roads and a description of compliance issue with the leaking valve/stained soil. Site supervisor Tony Kerns came to location along with the lease operator, isolated the leak and put a LOTO on valve to get it in compliance.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p> | revasr | 07/09/2020 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|---------------|---|
| 699302120 | location pics | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5193695 |