

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/09/2020

Submitted Date:

07/09/2020

Document Number:

700402319**FIELD INSPECTION FORM**
 Loc ID 399056 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 96850Name of Operator: TEP ROCKY MOUNTAIN LLCAddress: PO BOX 370City: PARACHUTE State: CO Zip: 81635**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Burger, Craig		craig.burger@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	
Katz, Aaron		aaron.katz@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Hayes, Mike	970-620-2257	hayespetroleum@gmail.com	
Abrams, Deborah		deborah.abrams@state.co.us	
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
89418	WELL	DA	08/08/1958	DA	103-40358	HUSKY OIL CO 5	DA

General Comment:

A follow up inspection of FIR documents:

- 1) 679702306 dated 12-21-2018
- 2) 692400563 dated 12-29-2018
- 3) 700402250 dated 7-2-2020

The following compliance issues are uncompleted:

- 1) Plug well & complete reclamation. Complete by 3-12-2019.

This inspection determined the current plug back depth is 16.5 feet.

This is a summary of inspection report 7004002319

LocationOverall Good: ☐

Emergency Contact Number:

Comment: No signs present. No P&A marker was located within 100' of the well or in the wellbore.

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Unused boards.		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Drilling mud located near the hole.		
Corrective Action:		Date:	

Overall Good: ☐

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 89418 Type: WELL API Number: 103-40358 Status: DA Insp. Status: DA**Idle Well**Purpose: ☐ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Well abandon in 1958 or 1959. Under the 5" thick cement cap with an 3" hole, the well bore diameter was measured at 12". No casing is visible.

The current plug back depth is 16.5 feet. A flashlight was inserted into the hole and a photo acquired of the top of the plug. Photo 2. The plug top surface is dirt.

Nearby loose boards were place over the open hole after the inspection was completed. Photo 3.

Corrective Action: Consult with NW Area Engineers as to proper Plugging & Abandonment procedures & complete Plugging / Reclamation of identified facilities by 3/12/19.

Date: 03/19/2019

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Other	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700402320	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5193771