

Inspection Photos

API: 055-06142

Operator: TABULA RASA ENERGY

Inspection Date: 7/9/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06142 | Date: 7/9/2020

Inspection Photos



Photo 1. Facing north along the access road. There are noxious weeds along the side of the road that need to be controlled. Noxious weeds observed were Common mullein and Musk thistle.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 7/9/2020

Inspection Photos



Photo 2. Facing toward the HARRY WILLIS 2 well. The operator sign has been updated with current emergency contact.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 7/9/2020

Inspection Photos



Photo 3. Facing toward the HARRY WILLIS 1 well. The operator sign has been updated with current emergency contact.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 7/9/2020

Inspection Photos



Photo 4. Facing west toward the location. There are noxious weeds at the location. Arrow points to Musk thistle, List B noxious weed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 7/9/2020

Inspection Photos



Photo 5. Facing south along the eastern fill slope. There are noxious weeds along the fill slope. Arrows points to Musk thistle, List B noxious weed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06142 | Date: 7/9/2020