

# Inspection Photos

ID: 324565

Operator: TABULA RASA ENERGY

Inspection Date: 7/8/2020



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

ID: 324565 | Date: 7/8/2020

## Inspection Photos



**Photo 1.** The gate at the beginning of the access road has fallen off the hinges and needs to be repaired.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 324565 | Date: 7/8/2020

## Inspection Photos



**Photo 2.** Facing northwest toward the location. There are noxious weeds at the location. Arrow points to Musk thistle, List B noxious weed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 324565 | Date: 7/8/2020

## Inspection Photos



**Photo 3.** There are numerous Musk thistle rosettes observed at the location which need to be controlled.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 324565 | Date: 7/8/2020

## Inspection Photos



**Photo 4.** This noxious weed is Houndstoungeweed which seed has developed which needs to be bagged and removed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 324565 | Date: 7/8/2020

## Inspection Photos



**Photo 5.** The well sign is posted at the well head.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

ID: 324565 | Date: 7/8/2020