

Inspection Photos

API: 055-06306

Operator: MANZANO LLC

Inspection Date: 7/8/2020



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06306 | Date: 7/8/2020

Inspection Photos



Photo 1. Facing west at the beginning of the access road. The access road has not been reclaimed and the cattle guard and gate remain.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06306 | Date: 7/8/2020

Inspection Photos



Photo 2. Facing northeast where road crosses the stream. Road was not reclaimed and culvert remains.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06306 | Date: 7/8/2020

Inspection Photos



Photo 3. Facing northeast along the access road ascending the hill side. Access road has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06306 | Date: 7/8/2020

Inspection Photos



Photo 4. Facing north along access road. Arrow points to the well pad which is not recontoured.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06306 | Date: 7/8/2020

Inspection Photos



Photo 5. Facing northwest toward the fill slope of the location. There are numerous Musk thistle noxious weeds in this area of the well pad and access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06306 | Date: 7/8/2020

Inspection Photos



Photo 6. Facing southeast toward the access road and location shown in the right side of the photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06306 | Date: 7/8/2020

Inspection Photos



Photo 7. Facing southwest toward the location. The location has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06306 | Date: 7/8/2020

Inspection Photos



Photo 8. Gravel remains throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06306 | Date: 7/8/2020

Inspection Photos



Photo 9. Facing southwest toward the cut slope of the location which is approximately 12 ft. height.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06306 | Date: 7/8/2020

Inspection Photos



Photo 10. Facing northwest toward the cut slope of the location which is approximately 12 ft. height.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06306 | Date: 7/8/2020

Inspection Photos



Photo 11. Facing northeast along the fill slope of the well pad.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06306 | Date: 7/8/2020

Inspection Photos




Photo 12. East side of the location facing west.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06306 | Date: 7/8/2020

Inspection Photos



Photo 13. Facing east toward the fill slope. This area of the fill slope has been partially excavated and consists of numerous noxious weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06306 | Date: 7/8/2020

Inspection Photos



Photo 14. Facing east toward the surrounding undisturbed area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06306 | Date: 7/8/2020