

Inspection Photos
Location Name: TINA 32-27
API#: 05-071-06796
INSP. #: 695102935



PHOTO 1: LOCATION



PHOTO 2: WELL SIGN



Inspection Photos
Location Name: TINA 32-27
API#: 05-071-06796
INSP. #: 695102935



PHOTO 3: AREA OF IMPACTED SOIL NEAR LOW CORNER OF COMPRESSOR SKID. Conduct maintenance on equipment, cleanup stained material and review self inspection processes PER RULE 1002.f.(2)F. CA DATE 7-20-20.



PHOTO 4: STANDING OILY FLUID IN COMPRESSOR SKID. Comply with general provisions of the oil and gas act for wildlife protection. CA DATE 7-20-20.

Inspection Photos
Location Name: TINA 32-27
API#: 05-071-06796
INSP. #: 695102935



PHOTO 5: UNUSED EQUIPMENT STORED ON LOCATION. REMOVE UNUSED EQUIPMENT PER RULE 603.f. CA DATE 10-13-2020



PHOTO 6: FORM 4 HAS BEEN APPROVED DOC #402095372