

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/13/2020

Submitted Date:

07/13/2020

Document Number:

700701074**FIELD INSPECTION FORM**Loc ID 334821 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211052	WELL	PR	06/15/2002	GW	045-06810	COUEY T8-42	PR
261758	WELL	PR	08/07/2002	GW	045-07975	COUEY 8-10B	PR
261759	WELL	PR	05/16/2002	GW	045-07976	COUEY 8-10A	PR

General Comment:**COGCC Inspection Report Summary**

On Monday 7/13/20 at approximately 9:00 AM, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus J8E, at Location # 334821 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year.

During this inspection the following possible compliance issues were observed:

- Debris, piping

Refer to photograph of observed compliance issue. The pumper came onto location and I informed him of the possible compliance issue and he removed debris while I was on location. no follow up is needed.

This is a summary of inspection report.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒**Signs/Marker:**

Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	DEBRIS		
Comment:	pipin in random spots on location and debris was removed by pumper while on location.		
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

Equipment:				corrective date
Type: Ancillary equipment	# 1			
Comment:	500 gallon methanol tank in tank battery			
Corrective Action:				Date:
Type: Bird Protectors	# 3			
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 3			
Comment:				
Corrective Action:				Date:
Type: Pig Station	# 1			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 4			
Comment:	All meters calibrated on location within a year.			
Corrective Action:				Date:
Type: Plunger Lift	# 3			
Comment:				
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 3			
Comment:				
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
			Date:	

Venting:

Yes/No	NO		
--------	----	--	--

Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected FacilitiesFacility ID: 211052 Type: WELL API Number: 045-06810 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 261758 Type: WELL API Number: 045-07975 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 261759 Type: WELL API Number: 045-07976 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
Berms		Ditches				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700701081	Photos for J8E	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5195189