

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/15/2020

Submitted Date:

07/15/2020

Document Number:

690006219

FIELD INSPECTION FORM

 Loc ID 436028 Inspector Name: Carlile, Craig On-Site Inspection 2A Doc Num: _____
Operator Information:
 OGCC Operator Number: 47120
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
 Address: P O BOX 173779
 City: DENVER State: CO Zip: 80217-
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, Inspections		COGCCinspections@Anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436024	WELL	PR	11/17/2014	OW	123-38894	BERRY FARMS 32N-8HZ	PR
436025	WELL	SI	01/01/2020	OW	123-38895	BERRY FARMS 31N-8HZ	SI
436026	WELL	PR	11/28/2014	OW	123-38896	BERRY FARMS 31C-8HZ	PR
436027	WELL	SI	03/01/2020	OW	123-38897	BERRY FARMS 32C-8HZ	SI
436065	WELL	PR	11/24/2014	OW	123-38911	BERRY FARMS 30N-8HZ	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:

					corrective date
Type: Plunger Lift	# 5				
Comment:					
Corrective Action:		Date:			

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Shared battery location number: 436576				
Corrective Action:		Date:			

Paint

Condition			
Other (Content)			
Other (Capacity)			
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:		Date:		

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 436024 Type: WELL API Number: 123-38894 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 436025 Type: WELL API Number: 123-38895 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In

Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action:

Date: _____

Facility ID: 436026 Type: WELL API Number: 123-38896 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Facility ID: 436027 Type: WELL API Number: 123-38897 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In

Temporarily Abandoned

Reminder: _____

Comment: SI

Corrective Action:

Date: _____

Facility ID: 436065 Type: WELL API Number: 123-38911 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine wellhead inspection.	carlilec	07/15/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690006220	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5196746