

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /13NWNW

Location ID: 312601



Photo #1521 from entrance to location




Photo #0979 from inspection #699800920 inspection conducted on 4/15/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /13NWNW

Location ID: 312601




Photo #1522 Tank capacity not labeled.



Photo #0980 from inspection #699800920 inspection conducted on 4/15/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /13NWNW

Location ID: 312601



Photo #1524 Multiple places with debris on location.



Photo #0981 from inspection #699800920 inspection conducted on 4/15/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /13NWNW

Location ID: 312601



Photo #1523 Multiple places with debris on location.