

# Inspection Photos

7/14/2020

Operator: CAERUS PICEANCE LLC - 10456

Location ID: 335667

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335667



**Photo 1:** Photo taken from the northwest end of the Location, facing north. Photo shows excavated areas due to dumpline spill.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335667



**Photo 2:** Photo taken from the northwest end of the Location, facing northwest. Photo shows excavated areas due to dumpline spill, and the soil stockpiles.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335667



**Photo 3:** Photo taken from the west end of the Location, facing northeast. Photo shows BMPs to prevent sediment transport from the soil stockpiles are missing or insufficient.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335667



**Photo 4:** Photo taken from the west of the Location, facing northeast. Photo shows BMPs to prevent sediment transport from the soil stockpiles are missing or insufficient.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335667



**Photo 5:** Photo taken from the north end of the Location, facing west. Photo shows BMPs to prevent sediment transport from the soil stockpiles are missing or insufficient.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335667



**Photo 6:** Photo taken from the north end of the Location, facing east. Photo shows BMPs to prevent sediment transport from the soil stockpiles are missing or insufficient.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335667



**Photo 7:** Photo taken with use of a west end of the Location. Photo shows straw hay bale BMPs along the west end of the Location is has not been maintained and is not in proper functioning condition.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335667



**Photo 8:** Photo taken from the northwest end of the Location. Photo shows excavated areas due to dumpline spill.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335667



**Photo 9:** Photo taken from the northeast end of the Location, facing east. Photo shows equipment and 2<sup>nd</sup> area of the Location where excavation activities are evident.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335667



**Photo 10:** Photo shows excavated area on the northeast end of the Location.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335667



**Photo 11:** Photo of soil stockpile on the northeast end of the Location.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335667



**Photo 12:** Photo of riser on the west end of the Location.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC - 10456  
Location ID: 335667



**Photo 12:** Photo shows what appears to be processed piping on the west end of the Location. It is unclear as to what the current application and future use of the equipment is on the Location.