

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/14/2020

Submitted Date:

07/17/2020

Document Number:

691201342**FIELD INSPECTION FORM**
 Loc ID 318189 Inspector Name: Graber, Candice (Nikki) On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 52530Name of Operator: MAGPIE OPERATING INCAddress: 2707 SOUTH COUNTY RD 11City: LOVELAND State: CO Zip: 80537**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Oil, Magpie		magpieoil@yahoo.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240824	WELL	SI	10/01/2019	OW	123-08612	SCHRAGE 1	EI
451018	TANK BATTERY	AC	06/09/2017		-	Schrage Tank Battery	EI

General Comment:

COGCC Environmental Inspection to determine the status of pit 10926. The pit location was determined based on historical documents and aerial imagery and was located south of and adjacent to current tank battery berm. COGCC personnel found no surface indication of a pit present in the location. The pit status has been changed to closed. Refer to Remediation #3969 for additional closure details.

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Good

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	<u>Noxious weeds around former pit area.</u>		
Corrective Action:	<u>Comply with Rule 1003.f.</u>		Date: <u>08/01/2020</u>

Overall Good: ☐

Spills:				
Type	Area	Volume		
Condensate	Valve	<= 1 bbl		
Comment:	<u>Stained soil was observed at the valve within the tank battery berm</u>			
Corrective Action:	<u>Properly treat or dispose of oily waste in accordance with 907.e.</u>		Date:	<u>08/01/2020</u>
Comment:	<u>Stained soil was observed at the base of the vertical separator.</u>			
Corrective Action:	<u>Properly treat or dispose of oily waste in accordance with 907.e.</u>		Date:	<u>08/01/2020</u>

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	240824	Type:	WELL	API Number:	123-08612	Status:	SI	Insp. Status:	EI
Facility ID:	451018	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	EI

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691201343	Pit Status Form	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5198652
691201344	Staining inside tank berm	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5198653
691201345	Staining at separator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5198654
691201346	Weeds at former pit area	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5198655