

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

07/16/2020

Submitted Date:

07/17/2020

Document Number:

690101981**FIELD INSPECTION FORM**
 Loc ID 318921 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		cogccinspections@anadarko.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242488	WELL	PA	03/08/2018	OW	123-10279	C A FORD UNIT 2	PA
464214	OFF-LOCATION FLOWLINE	AC	04/29/2019		-	Wellhead Line 16SESE	EG
464215	OFF-LOCATION FLOWLINE	AC	04/29/2019		-	Wellhead Line 16SESE	EG

General Comment:

Engineering Integrity Inspection; Flowline Inspection
Photo Uploaded

Inspected Facilities

Facility ID: 242488 Type: WELL API Number: 123-10279 Status: PA Insp. Status: PA

Flowline

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well (C A Ford Unit 2) has been plugged and abandoned; COGCC form 42 notice of start of plugging operations Doc #401546916 was received on 02/15/2018. The facility/ battery has been decommissioned/ equipment removed. The off location flowline was approximately 295' long between/ W from the facility to the (PA) well; this flowline appears to have been abandoned in place. COGCC Form 42 notice of flowline abandoned in place Doc #401588245 was received on 03/27/2018. No flowline risers were observed at the (PA) well or facility/ battery areas. No Noble Energy or contract personnel were on site at the time of this field inspection.

Corrective Action:

Date:

Facility ID: 464214 Type: OFF- API Number: - Status: AC Insp. Status: EG

Facility ID: 464215 Type: OFF- API Number: - Status: AC Insp. Status: EG

COGCC Comments

Comment	User	Date
Note: There is (1) disconnected/ out of service gas gathering meter run on location: The following COGCC final reclamation rule(s) are applicable: COGCC Rule 1004. FINAL RECLAMATION OF WELL SITES AND ASSOCIATED PRODUCTION FACILITIES (partial description of rule) a. Well sites and associated production facilities. Upon the plugging and abandonment of a well, all pits, mouse and rat holes and cellars shall be backfilled. All debris, abandoned gathering line risers and flowline risers, and surface equipment shall be removed within three (3) months of plugging a well.	maclarej	07/17/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101982	Location photo; OOS gas meter run	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5198749