

Inspection Photos

Operator: Kinder Morgan
API: 083-06624
Date: 7/9/2020



Photo 1. View of the access road facing southward. Revegetation appears to be progressing with crested wheatgrass, fourwing saltbush, smooth brome, and western wheatgrass.



Photo 2. View of the project area from the northwestern corner facing center.





Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of riser at the entrance to the former well pad, is not maintained and appears to be associated with the plugged well. Riser should be removed.



Photo 5. View of riser in the southeastern project area. Flowline maps do not illustrate active lines in the area. Riser needs to be removed.



Photos 6/7. View of Russian knapweeds within the project area. Approximately 3000 individuals observed.



Photo 8. View of reference area vegetation comprised of pinyon and juniper woodland, with sagebrush, yucca, antelope bitterbrush, Indian ricegrass, and Navajo tea in the understory.