



Photo # 1 –

Location Name: – Schneider Energy Services, Inc. - Facility ID 313815 – Rem #3215
Inspection Date: 07/14/2020



Photo # 2 – West side of tank battery, oily soil under tanks and valves

Location Name: – Schneider Energy Services, Inc. - Facility ID 313815 – Rem #3215
Inspection Date: 07/14/2020



Photo # 3 – East side of tank battery, oily soil under valves and bottom of north tank

Location Name: – Schneider Energy Services, Inc. - Facility ID 313815 – Rem #3215
Inspection Date: 07/14/2020



Photo # 4 – East side berm of tank battery, animal burrows

Location Name: – Schneider Energy Services, Inc. - Facility ID 313815 – Rem #3215
Inspection Date: 07/14/2020



Photo # 5 – North side of northern tank, oil stained soil and tanks leaking from corrosion holes



Location Name: – Schneider Energy Services, Inc. - Facility ID 313815 – Rem #3215
Inspection Date: 07/14/2020



Photo # 6 – Northwest side of northern tank, oil stained soil and tank leaking from corrosion holes

Location Name: – Schneider Energy Services, Inc. - Facility ID 313815 – Rem #3215
Inspection Date: 07/14/2020



Photo # 7 – Northwest side of northern tank, oil stained soil and tank leaking from corrosion holes (also south tank)



Location Name: – Schneider Energy Services, Inc. - Facility ID 313815 – Rem #3215
Inspection Date: 07/14/2020



Photo # 8 – Northwest side of southern tank, oil stained soil and tank leaking from corrosion holes



Location Name: – Schneider Energy Services, Inc. - Facility ID 313815 – Rem #3215
Inspection Date: 07/14/2020



Photo # 9 –

Location Name: – Schneider Energy Services, Inc. - Facility ID 313815 – Rem #3215
Inspection Date: 07/14/2020



Photo # 10 – BMPs need to be maintained north of skim tank

Location Name: – Schneider Energy Services, Inc. - Facility ID 313815 – Rem #3215
Inspection Date: 07/14/2020



Photo # 11 – Berms need to be maintained north of skim tank



Location Name: – Schneider Energy Services, Inc. - Facility ID 313815 – Rem #3215
Inspection Date: 07/14/2020



Photo # 12 – View northeast from SW corner of Pit 102699



Location Name: – Schneider Energy Services, Inc. - Facility ID 313815 – Rem #3215
Inspection Date: 07/14/2020



Photo # 13 – View west from SW corner of Pit 102699



Location Name: – Schneider Energy Services, Inc. - Facility ID 313815 – Rem #3215
Inspection Date: 07/14/2020



Photo # 14 – View northwest from NW corner of Pit 102699



Location Name: – Schneider Energy Services, Inc. - Facility ID 313815 – Rem #3215
Inspection Date: 07/14/2020



Photo # 15 – View north from Pit 102699, BMPs require maintenance

