

Inspection Photos

API: 017-07727

Operator: HIGH PLAINS ENERGY LLC

Inspection Date: 7/13/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 017-07727 | Date: 7/13/2020

Inspection Photos



Photo 1. Facing north along the access road toward the location. Location sign is posted next to access road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/13/2020

Inspection Photos



Photo 2. Facing northeast toward the location. There are pipe risers shown at red arrow.



Photo 3. View of pipe risers with no LOTO.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos



Photo 4. Facing east along the soil pile. The soil pile has not been replaced and recontoured. There are undesirable weeds growing throughout the soil stock piles. There is an accumulation of weed debris throughout the soil stockpiles.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/13/2020

Inspection Photos



Photo 5. Facing east at the location. There is numerous unused equipment laying on the ground.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/13/2020

Inspection Photos



Photo 6. There is tank berms that remain and unused fence posts.



Photo 7. There is oily waste observed near the berm shown in previous photo.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos



Photo 8. There is various unused equipment and debris laying on the ground. There is a berm that remains in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/13/2020

Inspection Photos



Photo 9. Facing southwest toward the location. There are multiple berm areas, unused equipment, debris, electrical equipment, and storage shed in disrepair.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/13/2020

Inspection Photos



Photo 10. There is a shed in disrepair at the southeast side of the location. Various unused equipment remains near the shed.



Photo 11. View of inside the shed. There is various piping risers, and supplies inside the shed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/13/2020

Inspection Photos



Photo 12. Facing west at the south side of the location. There is weed debris along the soil stockpile which is a potential fire hazard. Various supplies, unused equipment is laying on the ground.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/13/2020

Inspection Photos



Photo 13. Facing northeast toward the east side of the pad. There is undesirable weeds (*Kochia* sp.) growing throughout this area. There is weed debris which is a potential fire hazard.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/13/2020

Inspection Photos



Photo 14. Facing toward the wellhead at the center of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/13/2020

Inspection Photos




Photo 15. There is electrical wires extending out of the ground near the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/13/2020

Inspection Photos



Photo 16. Facing southeast toward the location. Interim reclamation has not been performed. Unused areas of the location have not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/13/2020

Inspection Photos



Photo 17. Facing toward the northwest side of the location. There is erosion that has occurred off the fill slope and undesirable weed growth along the perimeter.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/13/2020

Inspection Photos



Photo 18. Facing toward west side of the location. There is electrical wiring extending out of the ground in this area. There is a cellar with exposed electrical wiring inside.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/13/2020

Inspection Photos



Photo 19. This cellar electrical box has exposed electrical wires.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/13/2020

Inspection Photos



Photo 20. East side o the location facing southeast. Unused areas of the location have not been reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07727 | Date: 7/13/2020