

Inspection Photos

API: 017-07268

Operator: WIEPKING-FULLERTON ENERGY LLC

Inspection Date: 7/13/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 017-07268 | Date: 7/13/2020

Inspection Photos



Photo 1. Facing east along the former two track access road which remains per approved variance.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07268 | Date: 7/13/2020

Inspection Photos



Photo 2. Facing south along portion of the access road which remains. This area of previous erosion has been regraded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07268 | Date: 7/13/2020

Inspection Photos



Photo 3. Facing west along the portion of the access road which has been reclaimed. This portion of the road has not reached 80% revegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07268 | Date: 7/13/2020

Inspection Photos



Photo 4. Facing southwest toward the location. Vegetation is well established throughout the location. The perimeter of the location is fenced.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07268 | Date: 7/13/2020

Inspection Photos



Photo 5. Facing southeast at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07268 | Date: 7/13/2020

Inspection Photos



Photo 6. Facing northeast toward the location. Vegetation is well established throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 017-07268 | Date: 7/13/2020