

Inspection Photos
Operator: Patara
API: 113-06107
Date: 7/14/2020



Photo 1. View of revegetation along the approximately 0.75 mile-long access road facing eastward. Revegetation is progressing with grasses such as western wheatgrass, Indian ricegrass, and crested wheatgrass.



Photo 2. View of revegetation along the approximately 0.75 mile-long access road facing westward.



Photo 3. View of the western portion of the reclaimed well pad facing northward from the southwestern corner. Revegetation is established and shrubs such as sagebrush and winterfat are becoming established.



Photo 4. View of the reclaimed well pad from the southwestern corner facing center.



Photo 5. View from the beginning of Transect 1- within the project area (along the access road) facing northward.



Photo 6. View from the end of Transect 1, facing southward.




Photo 7. View of reference area vegetation comprised of black sage/matt saltbush vegetation community, facing northwestward.



Photo 8. View of reference area east of the transect, comprised of black sage/James galleta dominated grass and shrubland.