

Inspection Photos
Operator: Patara
API: 113-06163
Date: 7/14/2020



Photo 1. View of revegetation along the access road, from the beginning access, facing northwestward. Revegetation is progressing with grasses such as western wheatgrass, squirreltail, smooth brome, and crested wheatgrass.



Photo 2. View of the access road from the former well pad entrance, facing southeastward.



Photo 3. View of the well pad from the well pad entrance facing center. Although vegetation was well established. Thousands of musk thistles have proliferated.



Photo 4. View of the southern portion of the former well pad facing westward.



Photo 5. View of the western project area from the southwestern corner facing northward.



Photo 6. View of reference area comprised of gambel oak woodland with understory of black sagebrush, potentilla, fringed sage, and squirreltail.