

Inspection Photos
Operator: Patara
API: 113-06207
Date: 7/16/2020



Photo 1. View of the reclaimed well pad from the well pad entrance westward. Revegetation is established with grasses such as western wheatgrass, Indian ricegrass, and shrubs/sub-shrubs such as rubber rabbitbrush and *Heterotheca villosa*. Young juniper trees are also becoming established.



Photo 2. View of the eastern project area from the southern edge facing northeastward.



Photo 3. Another view of revegetation on the well pad, facing northward.



Photo 4. View of the reclaimed access road from the well pad entrance facing southward.



Photo 5. View of Russian knapweeds observed along the access road.



Photo 6. View of reference area comprised of pinyon juniper woodland in a post-fire recovery conditions with grasses, shrubs, and forbs in the understory, such as western wheatgrass, needleandthread grass, black sage, and snakeweed.