

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type LOCATION

Comment: [Chain Link/ Fabricated fencing](#)

Corrective Action:

Date: _____

Equipment:

corrective date

Type: Bradenhead # 1

Comment:

Corrective Action:

Date: _____

Type: Ancillary equipment # 1

Comment: [Automation](#)

Corrective Action:

Date: _____

Venting:

Yes/No NO

Comment:

Corrective Action:

Date: _____

Flaring:

Type

Comment:

Corrective Action:

Date: _____

Inspected Facilities

Facility ID: 200845 Type: WELL API Number: 001-06248 Status: AC Insp. Status: AC

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection weather conditions were sunny and light wind. This location is a underground gas storage well.	medinaj	07/20/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699501538	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5199734