

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/20/2020

Submitted Date:

07/20/2020

Document Number:

696103356**FIELD INSPECTION FORM**Loc ID 332492 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 69175Name of Operator: PDC ENERGY INCAddress: 1775 SHERMAN STREET - STE 3000City: DENVER State: CO Zip: 80203**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**9 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
273561	WELL	SI	12/01/2018	OW	123-22375	CORNISH 11-3	PA

**General Comment:**

This is a **PLUGGED & ABANDONED WELL / CEMENTING** inspection.

Well(s): 1: Plugged & Abandoned | PA.

Plugging Operations / Cementing in progress. Final plug.

Battery: Inactive | Shut-down.

Inactive Battery SE corner GPS coordinates: 40.522709, -104.431355

**Location****Lease Road:**

Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	OTHER		
Comment:	Workover rig safety signage present.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment:		
Corrective Action:		Date: _____

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

			corrective date
Type: Plunger Lift	# 0		
Comment:	Plugged & Abandoned   PA. Equipment removed.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	Cement filled to top Casing & Surface casing appears at surface.		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 273561 Type: WELL API Number: 123-22375 Status: SI Insp. Status: PA**Cement**Cement ContractorContractor Name: Ranger Energy

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging OperationsDepth Plugs(feet range): 1670' - 0'Cement Volume (sx): 130 sxsGood Return During Job: YESCement Type: Class "G" 15.8#Comment: [Reference Form 42 doc. #402444509 indicates plugging start date: 07/17/2020. Approved.](#)

Safety meeting and complete daily JSA, check pressure tubing 0, casing 0, and bradenhead 0 open to work tank , RU Cementers ; Mix and pump 130 sacks of 15.8 # class G ,26.6 bbls total, from 1670' to surface LD all tubing ND BOP .Top off and verify cement to surface. Rack up pump and tank and rig down. Clean location.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On MON 07/20/2020 at approximately 08:14 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: PDC ENERGY INC  Location Name: CORNISH-66N63W /3NWNW  Location ID: 332492  Well Name: Cornish 11-3  API: 05-123-22375  Location County: Weld County, Colorado  Weather: Partly cloudy, dry.</p> <p>While there, I observed:  Well(s): 1: Plugged &amp; Abandoned   PA.  Plugging Operations / Cementing in progress. Final plug.  Battery: Inactive   Shut-down.  Inactive Battery SE corner GPS coordinates: 40.522709, -104.431355</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	07/20/2020

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696103357	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5199976">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5199976</a>