

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/21/2020

Submitted Date:

07/21/2020

Document Number:

697001682**FIELD INSPECTION FORM**Loc ID 318189 Inspector Name: Peterson, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 52530Name of Operator: MAGPIE OPERATING INCAddress: 2707 SOUTH COUNTY RD 11City: LOVELAND State: CO Zip: 80537**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Graber, Nikki		nikki.graber@state.co.us	
Warner, Ryan	970-669-6308	magpieoil@yahoo.com	
Warner, Ross		ross.magpieoil@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240824	WELL	SI	10/01/2019	OW	123-08612	SCHRAGE 1	SI
451018	TANK BATTERY	AC	06/09/2017		-	Schrage Tank Battery	AC

General Comment:

Form 42 #402441791, MIT for verification of repairs. All previous corrective actions from prior inspection document #691201342 remain in effect.

Location

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	HZ safety prep		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	WEEDS		
Comment:	Noxious weeds around former pit area.		
Corrective Action:	Comply with Rule 1003.f.	Date:	08/01/2020

Overall Good: ☐

Spills:			
Type	Area	Volume	
Comment:	Stained soil was observed at the base of the vertical separator.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.		Date: 08/01/2020
Condensate	Valve	<= 1 bbl	
Comment:	Stained soil was observed at the valve within the tank battery berm		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e.		Date: 08/01/2020

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Pipe fencing		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Bradenhead valve is exposed at surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 240824 Type: WELL API Number: 123-08612 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: MIT for verification of repairs. Perforations are 4564'-4896', CIBP set @ 4500', ICP @ 0 psig, pressure csg to 470 psig and isolate wellbore from pressure truck. 5 minute csg @ 470 psig, 10 minute csg @ 470 psig, 15 minute csg @ 470 psig, release pressure, SIW.

Corrective Action: _____ Date: _____

Facility ID: 451018 Type: TANK API Number: - Status: AC Insp. Status: AC

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☐ NO SURFACE INDICATION OF PIT