

Inspection Photos
Operator Name: LARAMIE ENERGY LLC
Facility ID: 312626



Entrance sign



Stormwater BMP's installed

Inspection Photos
Operator Name: LARAMIE ENERGY LLC
Facility ID: 312626



Flowline being exposed



Flowline removed from excavation

Inspection Photos
Operator Name: LARAMIE ENERGY LLC
Facility ID: 312626



Flowline removed from excavation



**Location picture after flowline removal,
No risers present**