

FORM  
INSPRev  
X/15

## State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/21/2020

Submitted Date:

07/21/2020

Document Number:

693200702

### FIELD INSPECTION FORM

Loc ID 312626 Inspector Name: Murray, Richard On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1401City: DENVER State: CO Zip: 80202**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	<a href="#">Engineering Integrity Supervisor</a>
		cogccnotifications@laramie-energy.com	<a href="#">All inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222055	WELL	SI	12/01/2019	GW	077-08657	HORSESHOE CANYON 2-29	PA

**General Comment:**

[Engineering Integrity Inspection performed on July 21, 2020, to verify flowlines on location were plug and abandon and no risers left on location](#)

[Form 42 received document number 402413798, FLOWLINE PRE-ABANDONMENT - 30-day notice of On-Location Flowline](#)

**Inspected Facilities**

Facility ID: 222055 Type: WELL API Number: 077-08657 Status: SI Insp. Status: PA

**Flowline**

#1	Type: Dump Line	3 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Dump Line Size: 2" Material: Carbon Steel  
 Variance: No Age: 5-10 Yrs Contents: Multiphase

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: 3 flowlines were abandoned, 1st flowline from wellhead to separator, 2nd flowline from separator to meter shed and 3rd separator to tank battery

Corrective Action: Date:

#2	Type: Sales Line	1 of Lines
----	------------------	------------

Flowline Description

Flowline Type: Sales Line Size: 6" Material: Carbon Steel  
 Variance: Age: 5-10 Yrs Contents: Natural Gas

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation  1102. Operations, Maintenance, and Repair  1103. Abandonment

Comment: Gas gathering flowline lateral was plugged and abandoned 6 months ago, flowline was abandoned on location and excavated 3 feet down next to gas meter shed and cap was welded on.

Corrective Action: Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200703	Photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5200869">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5200869</a>