

FORM  
INSPRev  
X/15

# State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

07/21/2020

Submitted Date:

07/21/2020

Document Number:

700701155

## FIELD INSPECTION FORM

Loc ID 334838 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10456  
Name of Operator: CAERUS PICEANCE LLC  
Address: 1001 17TH STREET #1600  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION  
 FOLLOW UP INSPECTION REQUIRED  
 NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211398	WELL	SI	09/01/2019	GW	045-07158	KRK 7-2	SI
262826	WELL	PR	08/28/2002	GW	045-08052	KRK 7-3B (B7)	PR
262828	WELL	PR	08/09/2002	GW	045-08054	K R K 7-2B (B7)	PR
262829	WELL	PR	08/09/2002	GW	045-08055	K R K 7-1B (B7)	PR

**General Comment:**

COGCC Inspection Report Summary  
On Tuesday 7/21/20 at approximately 2:00 PM, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus B7, at Location # 334838 in Garfield county Colorado.  
While there, I observed normal production operations. All meters have been calibrated on location within the past year.  
This is a summary of inspection report.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	BATTERY		
Comment:			
Corrective Action:			Date:
<b>Emergency Contact Number:</b>			
Comment:	911		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Bird Protectors	# 4		corrective date
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 5		
Comment:	All meters calibrated on location within a year.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:	shared containment with condensate tanks				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	2	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 211398 Type: WELL API Number: 045-07158 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: last produced 8/1/2019

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 262826 Type: WELL API Number: 045-08052 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 262828 Type: WELL API Number: 045-08054 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 262829 Type: WELL API Number: 045-08055 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms		Culverts				
Gravel		Ditches				
		Gravel				

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700701163	Photos for B7	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5200928">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5200928</a>