

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

07/21/2020

Submitted Date:

07/21/2020

Document Number:

699302161**FIELD INSPECTION FORM**Loc ID 422533 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10633Name of Operator: CRESTONE PEAK RESOURCES OPERATING LLCAddress: 1801 CALIFORNIA STREET #2500City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:14 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		Cogcc.inspections@crestone pr.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422571	WELL	PR	04/01/2017	OW	123-33312	MCCONAHAY 1A-34H	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Chainlink topped with barb wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Chainlink topped with barb wire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Chainlink topped with barb wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Chainlink topped with barb wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 6		
Comment:	automation		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		

Comment:		Date:	
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	card n meter house indicates current calibration	Date:	
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:		Date:	
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:		Date:	
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface	Date:	
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:		Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:	Date:				

Paint

Condition	
Other (Content)	
Other (Capacity)	210 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:	shares containment with condensate tanks			
Corrective Action:	Date:			

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	8	OTHER	STEEL AST		,
Comment:					
Corrective Action:	Date:				

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	330 bbl

Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Inspected Facilities

Facility ID: 422571 Type: WELL API Number: 123-33312 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 7/21/2020 at approximately 1455 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Crestone Peak Resources location:</p> <p style="text-align: right;">McConahay 1A-34H at</p> <p>API #05-123-33312 in Weld County Colorado.</p> <p>While there, I observed a wellsite and tank battery, Form 17 Doc # 402296115 submitted on 1-28-2020 and is approved.</p> <p>During this inspection no compliance issues were observed:</p> <p>See attached photos.</p> <p>Location is dry, weather is clear.</p> <p>No follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	07/21/2020

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699302162	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5200959